

## **X-RAY EMERGENCY PROCEDURES**

Individuals who suspect that they have been exposed to the direct beam from any x-ray producing equipment shall:

1. Immediately turn the equipment off.
2. Call the Radiation Safety Office at **231-5364** (before 5pm) or the Virginia Tech Police at **911** (after 5pm, or on weekends).
3. Notify one person from the laboratory line of authority.
4. Remain in the area until the arrival of the Radiation Safety Officer, or his designee.

### **EMERGENCY CONTACTS**

|                      |                                       |        |          |
|----------------------|---------------------------------------|--------|----------|
| Laboratory Authority | Dr. Ross Angel<br>2029 ILSB           | 1-7974 | 953-0147 |
| Secondary Contact    | Dr. Carla Slebodnick<br>2028 ILSB     | 1-1848 | 552-1662 |
| Other Contact        | Mr. Phil Burcham<br>1050 Derring Hall | 1-3840 | 577-9015 |
| Other Contact        | Dr. Jing Zhao<br>2027 ILSB            | 1-8921 | 320-1587 |

### **EMERGENCY TELEPHONE NUMBERS**

|                           | 8am-5pm | After 5pm |
|---------------------------|---------|-----------|
| Radiation Safety Office   | 1-5364  | 911       |
| Hazardous Material Safety | 1-8758  | 911       |
| Virginia Tech Police      | 911     | 911       |
| Rescue Squad              | 911     | 911       |
| Fire                      | 911     | 911       |